

Metala hoztu eta solidifikatzean bere barnean sortzen den hutsunea.

Revision #1

Created 20 June 2025 12:49:23 by Admin

Updated 20 June 2025 12:50:31 by Admin